

Cleaning and maintenance

- 1. Avoid direct contact of the product with food, especially with salty ingredients.
- 2. Use a soft textile to wipe the surface after usage to dry it thoroughly. Do not use abrasive materials for wiping.
- 3. After cleaning, store the product in a ventilated and dry environment. Otherwise, a wet environment could lead to flash rust.
- 4. The maximum capacity per shelve is 50 kg. Please do not overload.